25X1

## PRORTY

	1963 AUG	8 2	21 34 <b>Z</b> 9 A	UG 1963
			<sup>л</sup> ЛИС 196.	3
SUBJECT: MISSION 8863 PRELIMINARY ANALYSIS			HFS	***
1. CONSITENTLY RECOGNIZE MOTOR VEHICLES,	SMALL	AIRCR	AFT,	<u>*</u>
RUNWAY LETTERING AND MARKING, RAILROAD CARS.	c <del>c t</del>		<b>DN8</b>	

INDEX CAMERA SHUTTER DID NOT OPERATE. STELLAR PHOTOGRAPHY OBTAINED BUT FILM METERING WAS ERRATIC. CAUSE UNDETERMINED.

- Grace (File)]
- PHOTOGRAPHY GENERALLY SHOWS SOFT IMAGERY CAUSED BY:
- THERMAL CONDITIONS BEING 15 TO 20 DEGREES HIGHER THAN NOM INAL.
  - B. INSTRUMENT DYNAMICS.
- ERROR IN INC FROM INCORRECT CYCLING RATE OR VEHICLE ATTITUDE AND RATES.
  - 5. OBSERVATIONS MADE TO DATE SHOW:
    - SOME FRAMES HAVE LOCALIZED HIGH QUALITY.
- DURATION OF OPERATION WITHIN A PASS HAS NO OBSERVED EFFECT ON QUALITY.
  - DURATION OF MISSION HAS NO OBSERVED EFFECT ON QUALITY.

TOP SECRET

Declassification Review by NGA/DoD

Excluded from automatic dewngrading and

25X1

- D. NO DIRECT COMPARISON OF PRE AND POST ROLL JOINT OPERATION COULD BE MADE. HOWEVER, NO APPARENT DEGRADATION DUE TO ROLL JOINT HAS BEEN OBSERVED.
- E. PITCH AND ROLL DATA INDICATE GOOD VEHICLE STABILITY THROUGHOUT. YAW UNKNOWN AT PRESENT.
  - F. SOME DOUBLE IMAGERY OBSERVED IN A FEW INSTANCES.
- 6. MOST PROBABLE CAUSES OF DEGRADATION IN LIMITED OBSER-VATIONS MADE ARE:
  - A. TEMPERATURE
  - B. INC
  - C. DYNAMICS
  - 7. FAILURE ANALYSIS TO DATE SHOWS:
    - A. PAN CAMERA AND S/I CAMERA FAILED TO START ON PASS 23.
- B. TELEMETRY INDICATES DECODER PASSED CORRECT COMMANDS
  BUT INSTRUMENTS FAILED TO RESPOND.
- C. NO RESPONSE TO REAL TIME COMMAND AND VEHICLE BYPASSES DECODER.
- D. TESTING AT ON SUSPECTED COMPONENTS HAS THUS FAR FAILED TO DUPLICATE FAILURE.

8. EXPOSURE APPEARS TO BE CORRECT AND AS PREDICATED.

TOPSECRET

END OF MESSAGE

25X1